

Number	Synopsis	October 9, 2019 Status
BUG-000122121	When performing a cartographic realignment that is larger than the M tolerance but smaller than the default XY tolerance and the network is configured to update the measure for cartographic realignments, no calibrate edit log records are written, resulting in incorrect event behaviors being applied	Fixed in 10.8
BUG-000122847	Certain decimals change after manual inputting certain numbers in attributes within Event Editor	Fixed in 10.8
BUG-000123422	When Registering an Event from the ALRS Properties window, Event behaviors will reset to defaults	Fixed in 10.8
BUG-000121008	Retiring a portion of a gapped route will sometimes retire the wrong portion.	Fixed at 10.7.1
BUG-000121031	Relocate event tool error in Roads and Highways 10.6.1 : 'Object reference not set to an instance of an object'	Fixed at 10.7.1
BUG-000122029	Incorrect measure values are applied to the line events when a realignment between a gap is performed and the event behavior is set to Cover.	Fixed at 10.7.1
BUG-000122224	Incorrect measurement values on line events after realigning a part of a gapped route.	Fixed at 10.7.1
BUG-000115036	Line events created on a redline in Event Editor returns Route measures are null after creating the route and applying updates in ArcMap.	Fixed in 10.7
BUG-000117296	Conflicts are introduced on routes when doing calibration point edits while the route edits are being posted in another version	Fixed in 10.7
BUG-000118024	Ability to choose 'Null' when creating or reassigning route is not present, for extra attribute fields which are not a part of the route ID, with domains.	Fixed in 10.7
BUG-000118489	Incorrect measure values are assigned on events when a whole part of a gapped route is reassigned and the event behavior is set to Snap.	Fixed in 10.7
BUG-000118639	Incorrect measure values are assigned to events when a whole part of a gapped route is realigned with the Split Value, To Measure is set to the end of the gap and the event behavior is set to Cover.	Fixed in 10.7
BUG-000119545	Realign route does not apply the Cover event behavior correctly and applies incorrect measure values on gapped routes in different situations.	Fixed in 10.7
BUG-000119546	Extend route does not apply the Cover event behavior correctly on gapped routes.	Fixed in 10.7
BUG-000120670	Reassigning a portion of one gapped route to another gapped route shows incorrect calibration point values.	Fixed in 10.7
GIT166	Export Network: Some lollipop routes are returned as points in the LRM translation table.	Fixed in 10.7
GIT270	Create route fails when single field route ID includes the single quote character.	Fixed in 10.7

3 other issues being currently investigated

Issues fixed in 10.8 will be included in 10.7.1 patch

Issues fixed in 10.8, 10.7.1, and 10.7 will be included in 10.6.1 patch