

No Issue

About ArcGIS Pro

Product Information

ArcGIS Pro 2.9.3

Copyright ©2021 Esri Inc. All Rights Reserved

v2.9.3

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
September 12, 2022, 1:20:00 PM	3-PR-403-220912103102 / GN-5				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-403 / KM 1.3		LATTITUDE & LONGITUDE			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	2		Sign Codes Installed		
Posts Removed	2		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	2 ea	\$ 15	\$ 30.00		
4. Steel Flanged or Square Post Removal	2 ea	\$ 15	\$ 30.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 60.00		

DTOP Signing Report_5_1.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
August 25, 2022, 1:06:00 PM	3-PR-416-220825102243 / GN-12				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-416 / KM 2.3		LATTITUDE & LONGITUDE 18.357429 -67.180038			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	0		Sign Codes Installed		
Posts Removed	1		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	0 ea	\$ 15	\$ 0.00		
4. Steel Flanged or Square Post Removal	1 ea	\$ 15	\$ 15.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 15.00		

DTOP Signing Report_12_1.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
September 12, 2022, 1:09:00 PM	3-PR-403-220912101436 / GN-7				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-403 / KM 1.3		LATTITUDE & LONGITUDE			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	0		Sign Codes Installed		
Posts Removed	1		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	0 ea	\$ 15	\$ 0.00		
4. Steel Flanged or Square Post Removal	1 ea	\$ 15	\$ 15.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 15.00		

DTOP Signing Report_7_1.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
August 24, 2022, 5:18:00 PM	3-PR-416-22082414836 / GN-9				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-416 / KM 1.4		LATTITUDE & LONGITUDE 18.364243 -67.174648			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	4		Sign Codes Installed		
Posts Removed	2		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	4 ea	\$ 15	\$ 60.00		
4. Steel Flanged or Square Post Removal	2 ea	\$ 15	\$ 30.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 90.00		

DTOP Signing Report_9_1.pdf

Dynamic Image Issue

About ArcGIS Pro

Product Information

ArcGIS Pro 3.0.1

Copyright ©2022 Esri Inc. All Rights Reserved

v3.0.1

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
September 12, 2022, 1:20:00 PM	3-PR-403-220912103102 / GN-5				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-403 / KM 1.3		LATTITUDE & LONGITUDE			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	2		Sign Codes Installed		
Posts Removed	2		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	2 ea	\$ 15	\$ 30.00		
4. Steel Flanged or Square Post Removal	2 ea	\$ 15	\$ 30.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 60.00		

DTOP Signing Report_5_2.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
August 25, 2022, 1:06:00 PM	3-PR-416-220825102243 / GN-12				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-416 / KM 2.3		LATTITUDE & LONGITUDE 18.357429 -67.180038			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	0		Sign Codes Installed		
Posts Removed	1		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	0 ea	\$ 15	\$ 0.00		
4. Steel Flanged or Square Post Removal	1 ea	\$ 15	\$ 15.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 15.00		

DTOP Signing Report_12_2.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
September 12, 2022, 1:09:00 PM	3-PR-403-220912101436 / GN-7				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-403 / KM 1.3		LATTITUDE & LONGITUDE			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	0		Sign Codes Installed		
Posts Removed	1		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	0 ea	\$ 15	\$ 0.00		
4. Steel Flanged or Square Post Removal	1 ea	\$ 15	\$ 15.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 15.00		

DTOP Signing Report_7_2.pdf

DTOP TRAFFIC SIGNS MONITORING					
SITE INFORMATION		EXISTING CONDITION PHOTO			
INSPECTION DATE	TICKET NUMBER / GLOBAL NUMBER				
August 24, 2022, 5:18:00 PM	3-PR-416-22082414836 / GN-9				
FIELD PERSONNEL JoanBercedonis					
ROAD & KILOMETER PR-416 / KM 1.4		LATTITUDE & LONGITUDE 18.364243 -67.174648			
MUNICIPALITY Aguada		WORK PERFORMED Removed			
SIGN REMOVED			SIGN INSTALLED		
TASK	QTY	REMOVED PHOTO	TASK	QTY	INSTALLED SIGN PHOTO
Sign Plaques Removed	4		Sign Codes Installed		
Posts Removed	2		Sign Plaques Installed	0.00 SqFT	
Foundations Removed	0		Post Installed	0.00 LnFT	
WORK SUMMARY					
PAY ITEMS NO. & DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL		
3. Sign Removal	4 ea	\$ 15	\$ 60.00		
4. Steel Flanged or Square Post Removal	2 ea	\$ 15	\$ 30.00		
5. Steel Flanged or Square Foundation Removal	0 ea	\$ 15	\$ 0.00		
6. Signs	0.00 SqFT	\$ 15	\$ 0.00		
7. Sign Post Installation	0.00 LnFT	\$ 25	\$ 0.00		
Total Cost			\$ 90.00		

DTOP Signing Report_9_2.pdf