

GAUD Hydrant Flushing Damage Report Fall 2020

Manchester-East Winthrop

Inspected By:
Date : 09/16/2020
Page 1


Location: PRESCOTT ROAD AT 24" X-ING

Hydrant ID	Nozzle Size	Min Flush	Max Flush	Hose?	Angle?	Gauge	Chlorine	Time ON	Time OFF
458	2.5	40	50	50'	No	54	1	12:58	13:04

Type of damage:

1. Lawn damage (loam, seed and hay)
2. Driveway damage (gravel)
3. Driveway/road damage (pavement)
4. Hydrant damage

Additional details and photos: Damage to lawn, driveway, road and hydrant.



GAUD Hydrant Flushing Damage Report Fall 2020

Manchester-East Winthrop

Inspected By:


Date : 09/16/2020

Page 2

1:32 PM Wed May 29

Cancel Collect Submit

GPS accuracy 98.4 ft - required 30 ft



Used on 05/29/2019

Your Name:
Rick

Date discovered:
5/29/2019

Notes



Location: RTE. 17 @ LIONS CLUB

Hydrant ID	Nozzle Size	Min Flush	Max Flush	Hose?	Angle?	Gauge	Chlorine	Time ON	Time OFF
464	2.5	15	25	25'	No	54	1	13:00	13:18

GAUD Hydrant Flushing Damage Report Fall 2020

Manchester-East Winthrop

Inspected By:

Date : 09/16/2020


Page 3

--	--	--	--	--	--	--	--	--	--

Type of damage:

5. Driveway damage (gravel)
6. Hydrant damage

Additional details and photos: Driveway and other



GAUD Hydrant Flushing Damage Report Fall 2020

Manchester-East Winthrop

Inspected By:
Date : 09/16/2020
Page 4

